
HISTORIC LANDMARK COMMISSION STAFF REPORT

729 South 500 East Demolition of a Contributory Building

PLNHLC2012-00046 September 6, 2012



Applicant:

Susan Brown, Sandra Beck representative

Staff:

Ray Milliner (801)535-7645 or ray.milliner@slcgov.com

Zone:

RMF-30

Master Plan Designation:

Low Density Residential

Council District:

4. Luke Garrott

Lot Size:

.06 acre

Current Use:

Residential

Applicable Land Use Regulations:

- 21A.34.010
- 21A.34.020(K-M)

Notification

- Notice mailed on August 24, 2012
- Agenda posted on the Planning Division and Utah Public Meeting Notice websites August 24, 2012

Attachments:

- A. Application
- B. Documentation
- C. Photos
- D. Proposed Plans

Request

The applicant, Susan Brown, represented by Sandra Beck, is requesting Historic Landmark Commission approval for a Certificate of Appropriateness for the Demolition of a Contributing Structure at 729 South 500 East. The applicant would like to demolish the building and replace it with a single family home.

Recommendation

Staff recommends that the HLC defer a decision on the Certificate of Appropriateness for the demolition of a contributory building for up to one year so the applicant can make a bona fide effort to preserve the structure per Section 21A.34.010 (M) of the Zoning Ordinance, based on the finding that the request substantially complies with four (4) of the six (6) required standards.

Potential Motions

Approval: Because the petition meets all six standards of approval, I move that the Historic Landmark Commission review the petition, and grant the request for a certificate of appropriateness for the demolition of a contributory building subject to the following condition of approval.

1. Prior to the issue of a demolition permit; the applicant shall receive Historic Landmark Commission approval for the proposed new home on the site.

Denial: Because the petition meets two or less of the six standards of approval, I move that the Historic Landmark Commission deny the certificate of appropriateness for the demolition of a contributory building based on the following findings (Commissioner then states findings).

Deferment: Because the petition meets 4 of the six standards of approval, I move that the Historic Landmark Commission defer a decision on the Certificate of Appropriateness for the demolition of a contributory building for up to one year so the applicant can make a bona fide effort to preserve the structure per Section 21A.34.010(M) of the Zoning Ordinance.

Vicinity Map



Background

According to the 1994 Reconnaissance survey completed for the Central City area, the home was built in 1910 as a single family residence. No information regarding the architect or builder is given. The Structure at the time of the survey was rated as a "B" meaning it is a contributory structure to the Central City Historic District. The building is an example of Folk Victorian architecture with a pyramid roof, four post front porch spanning the entire front façade and a small dormer on the front roof. Detailing on the building is simple with very little ornamentation.

The home was occupied continuously since its construction in 1910 until it was significantly damaged by fire in 2006. The fire caused significant damage to the building, burning a hole in the roof, damaging the structure of the porch, ruining most of the original windows, and causing significant smoke and water damage to the interior and floors. After the fire, the applicant did not repair the building, and as a result, it has remained vacant. The building is currently boarded but is intermittently occupied by trespassers looking for shelter.

The property owner would like to demolish the building and replace it with a new single family home. To support their request, the petitioner has submitted a detailed engineering report that concludes that the building should be removed (see attachment A application for report). If the Commission finds that the building indeed

should be demolished, it would need to review the proposed home plans for compliance with the new construction standards in Section 21A.34.020 of the Zoning Ordinance (see attachment D for proposed plans).

Public Comments

To date, staff has received no public comments regarding this application.

Analysis and Findings

Demolition of a Contributing Structure

The Historic Landmark Commission reviews all requests for Certificate of Appropriateness for demolition of contributing structures. Commission action is based on compliance with six standards featured in Section 21A.34.020(L) of the Zoning Ordinance. The Ordinance provides the Commission with three options when making a decision:

- 1. If six of the standards are met, the Commission will approve the demolition request.
- 2. If two or less of the standards are met, the Commission must deny the request.
- 3. If the Historic Landmark Commission makes findings that three to five of the standards are met, the Commission may defer a decision for up to one year, during which time the applicant must conduct a bona fide effort to preserve the site. The one-year "clock" begins only when a "bona fide" effort has started. Section 21A.34.010(M) lists four actions that define bona fide effort:
 - 1) Marketing the property for sale or lease.
 - 2) Filing an application for alternative funding sources for preservation, such as federal or state preservation tax credits, Utah Heritage Revolving Fund loans, redevelopment agency loans, etc.;
 - 3) Filing an application for alternative uses if available or feasible, such as conditional uses, special exceptions, etc.; and
 - 4) Obtaining written statements from licensed building contractors or architects detailing the actual costs to rehabilitate the property

See the analysis section of this report for staff analysis if the six demolition standards.

If the demolition proposal is not resolved by application of the six standards, the petitioner may initiate an economic hardship process, wherein a panel of three (3) people is selected to determine if denying a request for demolition is an economic hardship. The Panel evaluates economic hardship by applying standards in Section 21A.34.020(K)(2) of the Ordinance. Findings and conclusions are then forwarded to the Historic Landmark Commission, who makes a final decision. The Commission's decision must be consistent with the findings presented by the Economic Review Panel, unless it finds by a three-quarter vote of a quorum that the Economic Review Panel either acted arbitrarily or based its report on an erroneous finding of fact.

Contributing Status

The 1994 reconnaissance level survey identifies this building as a "contributing" structure in the Central City Historic District Structures are considered to be contributing, according to the definition outlined in Section 21A.34.020(B)(2) of the Zoning Ordinance:

A contributing structure is a structure or site within an H Historic Preservation Overlay District that meets the criteria outlined in subsection C2 of this section and is of moderate importance to the city, state, region or nation because it imparts artistic, historic or cultural values. A contributing structure has its major character-defining features intact and although minor alterations may have occurred they are generally reversible. Historic material may have been covered but evidence indicates they are intact.

Standards of Review

Standard 1: The physical integrity of the site as defined in subsection (C)(2)(b) of this section is no longer evident.

Analysis: Subsection (C)(2)(b) states, "Physical integrity in terms of location, design, setting, materials, workmanship, feeling and association as defined by the National Park Service for the National Register of Historic Places"

The terms in Subsection (C)(2)(b) are defined by the National Park Service in National Register Bulletin 15 as follows:

Location: Location is the place where the historic property was constructed or the place where the historic event occurred.

Design: Design is the combination of elements that create the form, plan, space, structure and style of a property.

Setting: Setting is the physical environment of a historic property. Whereas location refers to the specific place where a property was built setting refers to the character of the place in which the property played its historic role.

Materials: Materials are the physical elements that were combined during a particular period of time and in a particular pattern or configuration to form a historic property.

Workmanship: Workmanship is the physical evidence of the crafts of a particular culture or people during any given period in history.

Feeling: Feeling is a property's expression of the aesthetic or historic sense of a particular period of time.

Association: Association is the direct line between an important historic event or person and a historic property.

To retain historic integrity a property will always possess several, and usually most of the aspects defined above. Properties must not only retain their essential physical features, but the features must be visible enough to convey their significance.

The building retains much of its historic massing, materials and simple architectural elements that define its historic function and character. Had it not been damaged by fire, there would be no question the physical integrity of the building remains. Nonetheless, repairs to components damaged in the fire will require significant changes, including removal of the fire damaged roof, upgrades to the foundation, shoring up exterior walls, replacement of windows, rebuilding the front porch and the interior. As a result, the materials, workmanship and feeling of the original structure will be significantly altered or lost when the building is renovated.

Finding: Staff finds that the physical integrity of this building as established in Section 21A.34.020(C)(2)(b) of the Zoning Ordinance is currently evident, however, changes necessary to

occupy the building will significantly diminish that integrity because the building will need to be extensively altered after damage sustained in a fire. The project **complies** with this standard.

Standard 2: The streetscape within the context of the H Historic Preservation Overlay District would not be negatively affected.

Analysis: There is a contributory building immediately to the north, followed by a vacant lot and a noncontributory apartment building. To the south is a contributory home. The contributory buildings were constructed during the period of significance of the Central City Historic District and are similar in scale and materials. 729 South 500 East is located mid block, is a utilitarian building with simple design features that are similar to other contributing buildings along the 500 East streetscape. The importance of the building comes from its association, along with many other buildings of similar design and features to the overall integrity of the Central City Historic District.

Because of the loss of physical integrity that will occur as part of the renovation of the building, it is unclear whether the home will continue to contribute to the neighborhood as it did before the fire. There will be significant changes to the roof, walls, windows, and porch that will considerably alter the design, materials and workmanship of the home.

Finding: Staff finds that the home was severely damaged in 2006 when it burned and much of the historic integrity of the building was destroyed or will be removed or altered if renovated. Nevertheless, staff finds that the complete loss of the home will have a greater negative effect on the 500 East streetscape, as it would remove a significant element of the surrounding historic fabric that could never be replaced. The project **does not comply** with this standard.

Standard 3: The demolition would not adversely affect the H historic preservation overlay district due to the surrounding non-contributing structures.

Analysis: Three of the four buildings along the 500 East street frontage are considered contributing with a grade of ("B"), meaning they contribute to the overall historic nature of the Central City Historic District. Because of the relative dearth of non-contributing structures in the area, the removal of this building would have an adverse impact on the Central City Historic District because it would remove a central component to an intact historic neighborhood. Nonetheless, much of the original historic integrity of this home was lost with the fire, and much more will be lost if and when the building is repaired and reoccupied. When the home burned, the adverse affect on the Central City Historic District has already occurred.

Finding: Staff finds that the home is in close proximity to other historic buildings both along 500 East and within the Central City Historic District as a whole. Its removal would weaken the architectural unity in the district as well as on the streetscape. Staff further finds that because of the damage caused by the 2006 fire, much of the physical integrity of the building was destroyed or will need to be removed or altered in order to make the building livable. Therefore, staff finds that the project **complies** with this standard.

Standard 4: The base zoning of the site is incompatible with the reuse of the structure.

Analysis: The property is zoned RMF-30, Low Density Multi-Family Residential. The future reuse of the building would be as a single family home, which is a permitted use in the RMF-30 zone.

Finding: Staff finds that any reuse of the building would be as a single family home, which is a compatible use with the RMF-30 zone. Therefore, staff finds that the project **does not** comply with this standard.

Standard 5: The reuse plan appears to be consistent with the standards outlined in subsection H of this section.

Analysis: The petitioner has submitted a re-use plan for a new single family home. Prior to the issue of a building permit, the structure will be reviewed by the HLC for compliance with the standards of review in the Zoning Ordinance as well as the Salt Lake City Historic District Design Guidelines.

Finding: The proposed project will substantially comply with this standard.

Standard 6: The site has not suffered from willful neglect, as evidenced by the following:

- i. Willful or negligent acts by the owner that deteriorates the structure.
- ii. Failure to perform normal maintenance and repairs.
- iii. Failure to diligently solicit and retain tenants, and
- iv. Failure to secure and board the structure if vacant.

Analysis and Finding: The building was damaged by fire in 2006 and has not been legally occupied since that time. Although the building has suffered damage because of this, the applicant has secured and boarded the building as required by City Ordinance and therefore, the proposal **complies** with this standard.

Summary

Staff finds that the proposed request for a certificate of appropriateness for the demolition of a contributory structure substantially complies with four (4) of the six (6) required standards, and therefore recommends that the HLC defer a decision on the Certificate of Appropriateness for the demolition of a contributory building for up to one year so the applicant can make a bona fide effort to preserve the structure per Section 21A.34.010(M) of the Zoning Ordinance.

Application



HLC: Demolition or Economic Hardship

Use for demolition of a contributing or non-contributing structure and economic hardship. Please use application for minor alterations for demolition of accessory structure.

OFFICE USE ONLY

Pernion No. PLNALCZOIZ-00046.

Date Received: 1-23-12

Reviewed By: Dankling.

	5.500	C. SCC, W. 51108
Project Name:		,
Name of Applicant: SUSAN Brown	- represe	Phone: Dy Sandra Beck
Address of Applicant:	Principa	1 Broker, Windsor Real Es
E-mail Address of Applicant Stheckre@amail.com		Cell/Fax: 801-635-047-
Applicant's Interest in Subject Property:		
Name of Property Owner: Susan Brown		Phone:
E-mail Address of Property Owner:		Cell/Fax:
County Tax ("Sidwell #"):	-009	Zoning: Rm30
Legal Description (if different than tax parcel		N I I I I
		Proposed Property Use
Legal Description (if different than tax parcel	number): Existing Property Use	Proposed Property Use
	number): Existing Property Use	
Legal Description (if different than tax parcel	number): Existing Property Use	Proposed Property Use Additional Fee
Legal Description (if different than tax parcel	Existing Property Use ssociate fee Application	
Legal Description (if different than tax parcel	Existing Property Use ssociate fee Application Fee	Additional Fee
Legal Description (if different than tax parcel Please Check Type of Application and submit a Type Demolition (non-contributing)	Existing Property Use ssociate fee Application Fee \$27.69	Additional Fee Plus cost of first class postage

All information submitted as part of the application may be copied and made public including professional architectural or

engineering drawings which will be made available to decision makers, public and any interested party.

File the complete application at:

SLC Planning Division 451 S State, Room 215 PO Box 145471 Salt Lake City, UT 84114-5480 Telephone: (801) 535-7700

Signature of Property Owner

Or authorized agent

Feb 2008

Sandra Beck for Susan Brown

ECONOMIC HARDSHIP WORKSHEET

The following information is requested by the applicant in order for the Economic Review Panel to make a fair determination of economic hardship. This information is outlined in the *Salt Lake City Code*, 21A.34.020.K

- 1. Application for Determination of Economic Hardship: please include the application.
- 2 Standards for Determination of Economic Hardship. The Historic Landmark Commission shall apply following standards and make findings concerning economic hardship.
 - a. The applicant's knowledge of the landmark designation at the time of acqusition, or whether property was designated subsequent to acquisition.

1 1 7 0	1 1
family home since !	954
b. The current level of economic re	turn on the property as considered in relation to the
following:	
i. Amount paid for the property:	sproperty was inherited by
Date of Purchase :	
Party from whom purchased :	her damily pasted away
Relationship (if any) between owne	
ii. Annual gross income from prop	erty: 199 \$10 income - house
previous three years	199 \$'s a burn out &
	199 \$ un inhabitable
Annual net income from property:	199 \$
previous three years	199 \$
	199 \$
Itemized operating and maintenand	ce expenses; depreciation deduction; annual cash flow
before and after debt service: for the	ne previous three years
Year : <u>199 2010</u> <u>utilities :</u>	\$ -O NA
maintenanc	re: \$ NA
other:\$	NA
depreciation	n deduction : \$
annual cash	flow before debt service : \$ NA
annual cash	flow after debt service: \$
Year: 199 70 utilities:	\$
maintenanc	e: sweed control troyn city
other · \$	Springt, Lynn out. annout \$2 h

depreciation deduction

	annual cash flow before debt service : \$
	annual cash flow after debt service : \$
Year: <u>199</u>	utilities: \$
	maintenance: \$
	other:\$
	depreciation deduction: \$
	annual cash flow before debt service: \$
	annual cash flow after debt service : \$
iii. Remaining balance	e on any mortgage or other financing: \$16,153 approx.
Annual debt service :	199 \$ 5400 " Critical
previous three years	199 · \$ same
	199 \$ same
,	N.D.
iv. Real estate taxes:	2011 \$ 1311
previous four years	199 2010 \$
	199 2009 \$
Assessed value of the	property according to the Salt Lake County Assessor:
previous two years	2011 \$ 45,700° pulled from
	199 2010 \$ 49,700 assessors page
	please attach copies of the valuation/tax notices
v. All appraisals obtai	ned within the past two years. Please attach to worksheet
	lue of the property immediately prior
to its designation as a	
	of the property as a Landmark Site
at the time of this appl	ication: \$25,000
· · · · · · · · · · · · · · · · · · ·	Cala de dia
vii. Form of ownershi	p of property: Sole proprie torship
	Ci C
i.e. sole proprietorship; for	profit or non-profit corporation; limited partnership; joint venture, etc.
viii Any State or Ec	ederal income tax returns on or relating to the property for the
previous two (2) years	
previous two (2) years	. preuse utiuch copies
c. The marketability of	the property for sale or lease, the price asked and offers received,
if any, within the previo	
	601 8-11
Date listed: 2-12-3	Realtor/Agency: <u>Sandra Beck</u> Windsor Real Estate
	Windsor Keal Estate

	200	OF-
Price Asked :	\$ 49,700	-11.1
Offer received:	\$ 42,0000	Date: 2-13-2011 - Withdrawn
Offer received:	\$ 27 00000	Date: 2-15-2011 - Withdrawn
Offer received:	\$25,00000	Date: 2-15-2011 - Backup / Withdrawr
Date listed :		Realtor/Agency:
Price Asked :	\$	1 . 1
Offer received:	\$ 25,000°°	Date: 3-30-2011 current contract
Offer received:		Date :
Offer received:	\$	Date :
,		

This determination can also include testimony and relevant documents regarding:

- i. Any real estate broker or firm engaged to sell or lease the property;
- ii. Reasonableness of the price or rent sought by the applicant;
- iii. Any advertisements placed for the sale or rent of the property. please attach any relevant documents
- **d.** The infeasibility of alternative uses that can earn a reasonable economic return for the property as considered in relation to the following:
 - i. A report from a licensed engineer or architect with experience in rehabilitation as to the structural soundness of any structures on the property and their suitability for rehabilitation;
 - **ii.** Estimate of the cost of the proposed construction, alteration, demolition, or removal, and an estimate of any additional cost that would be incurred to comply with the decision of the Historic Landmark Commission concerning the appropriateness of proposed alterations;

please attach any estimates. estimates should be as specific as possible.

please attach any reports. reports should be as specific as possible.

iii. Estimated market value of the property in the current condition after completion of the demolition and proposed new construction; and after renovation of the existing property for continued use;

Estimated market value of the property in current condition: \$25,000 offers to date to be stimated market value after demolition and new construction: \$270,000 bassed on Estimated market value after renovation of existing historic building: \$189,000 bassed becated please attach information on which estimates are based please see attached comporable bales.

iv. The testimony of an architect, developer, real estate consultant, appraiser, or other professional experienced in rehabilitation as to the economic feasibility of rehabilitation or reuse of the existing structure on the property. please attach copies of written testimonie e. The applicant will review the economic incentives and/or funding programs available through federal, state, city, or private programs.
Utah Heritage Foundation Low Interest Revolving Fund Loan Program. Contact person: Date:

Date:
Notes:
Utah State Historic Preservation Office. State and Federal Investment Tax Credits.
Contact person:
Date:
Notes:

I hereby certify that all of the information presented in this worksheet is correct and accurate to the best of my knowledge.

Sandra Beck for Susan Brown
Signature of applicant
(See listing agreement for authority attorn)

To Whom it May Concern:

After approximately a full year of work, with much help from city employees, we are very excited to present to you our plan for the property located at 729 South 500 East, SLC, UT 84102.

In addition to the Economic Hardship package we have submitted, we would also like to make a note that since the fire several years ago, this house has been inhabited by the homeless community despite all efforts by the city, property owner, and the police to keep it secure. We feel this is especially important to note because photos do not address the strong possibility of methamphetamine and other illegal drugs that would further contaminate this structure. There are needles etc, that suggest such drug use, as well as human waste currently there.

We feel we meet the Standards for Demolition Of a Contributing Structure as outlined almost completely and hope that our presentation supplies all the information you will need to render a decision.

Please call Mr. Ben Scribner for any further information you may need regarding the future plan, or Mrs. Sandra Beck for information on the current owner, or Economic Hardship information.

Thank you for your consideration in this matter.

Sincerely, Landra Beck. Representing

Sandra Beck, Principal Broker, Windsor Real Estate, 801-635-0422

Ben Scribner, Century 21, Everest Realty Group, 801-381-3595

Attachment B

Documentation

DRION GOFF

SALT' LAKE; CHTY CORPORATION

DEPARTMENT OF COMMUNITY & ECONOMIC DEVELOPMENT
BUILDING SERVICES DIVISION

FRANK B. GRAY

MARY DE LA MARE-SCHAEFER
DEPUTY DIRECTOR

ROBERT FARRINGTON, JR.

135 1 200

December 30, 2009

Larry Richardson Salt Lake County Treasurer 2001 South State Street, N1200 Salt Lake City, UT 84115

Attention: John Nelson

Dear Mr. Nelson:

RE:

Boarding and/or Permit to Board fees of property located at 729 South 500 East,

Salt Lake City, Utah

Sidwell Number: 16-07-229-009

To certify a lien under Salt Lake City Code 9.16 and Title 10-11-1 Utah Code Annotated, for the placement upon the tax rolls.

Upon placement on said rolls the lien and all accrued interest shall be collected and subject to the same provisions governing general property tax.

Lien in the amount of \$1,375.00.

Sincerélý,

Phillip Booth

Housing/Zoning Officer

JOD VIED VIED CT-18

ORION GOFF BUILDING OFFICIAL

DEPARTMENT OF COMMUNITY & ECONOMIC DEVELOPMENT BUILDING SERVICES DIVISION

FRANK B. GRAY DIRECTOR

MARY DE LA MARE-SCHAEFER DEPUTY DIRECTOR

ROBERT FARRINGTON, JR.

DEPUTY DIRECTOR

Date Issued: December 30, 2009

Certified Mail: 7005 0390 0000 0378 6400

Susan A. Brown PO Box 18488 Salt Lake City, UT 84118

Dear Property Owner:

Re: Property located at 729 South 500 East, Salt Lake City, Utah

Sidwell Number: 16-07-229-009

On or about May 20, 2008, the property at the above referenced address was boarded. Salt Lake City Ordinance Title 18.48 requires a Permit To Board be obtained before a property may be boarded. The following charges reflect yearly fees for failure to obtain a Permit To Board, after you failed to comply with the Notice and Order dated December 17, 2009.

In accordance with the law, you are being sent this itemized statement of all costs.

Building and Housing administrative expenses \$ 100.00 Cost of boarding \$1,200.00 Late fees \$ 75.00

Total Due \$1,375.00

You are to reimburse Salt Lake City Corporation for these costs by sending payment to: **COMMUNITY & ECONOMIC DEVELOPMENT** Housing & Zoning Enforcement

City and County Building Room 406 451 South State Street, PO Box 145481 Salt Lake City, UT 84114

IF PAYMENT IS NOT RECEIVED WITHIN TWENTY (20) DAYS FROM THE DATE OF THIS LETTER, A LIEN FOR THE TOTAL AMOUNT WILL BE ATTACHED TO YOUR NEXT PROPERTY/TAX NOTICE.

Sincere

Phillip Booth

Housing/Zóning Officer

1210(8)

OFFICIAL CHECK

0603212254

Operator I.D.: utah2064

utah2808

March 19, 2010

PAY TO THE ORDER OF

***SALT LAKE COUNTY TREASURER ***

RE: #16-07-229-009-0000202

Six thousand seventy-two dollars and 08 cents

\$6,072.08

VOID IF OVER US \$ 6,072.08

WELLS FARGO & COMPANY ISSUER 420 MONTGOMERY STREET SAN FRANCISCO, CA 94163 PAYABLE AT WELLS FARGO BANK, N.A.

FOR INQUIRIES CALL (480) 394-3122

#OBO3212254# #121000248#4861 505626#

MPP Form 3 (12/03)

Make Checks Payable To:

SRLT LRKE COUNTY

SALT LAKE COUNTY TREASURER P. O. Box 410418

SLC, UT 84141-0418 2010 TAX SALE

16-07-229-009-0000

202

DELINQUENT PAYMENT 6,072.08

AMOUNT ENCLOSED

IMPORTANT! PLEASE READ!

- CASH MAILED AT TAXPAYER'S RISK, COUPON MUST

- PLEASE PRINT PARCEL NUMBER(S) ON YOUR CHECK

- YOUR CANCELLED CHECK IS YOUR RECEIPT.

BROWN, SUSAN A PO BOX 18488 SALT LAKE CITY

84118-0488

REQUEST FOR CHANGE OF MAILING ADDRESS

NAME **ADDRESS**

CITY & STATE

ZIP CODE

I certify that I am entitled to receive the property tax notice on this parcel. Any false statements or omissions are punishable under Utah law by a fine and/or imprisonment.

Name or Corporate Title, Please print or type

1329 2010 0020 0202 1F07554004000000 00000F07508 5

y lit san enter a constant

SALT LAKE COUNTY TREASURER 2001 S STATE ST #N1200 SALT LAKE CITY UT 84190-1250



March 24, 2010

Susan A Brown PO Box 18488 Salt Lake City UT 84118-0488

Re: Statement of Delinquent Taxes Due

Parcel Number 16-07-229-009-0000

Dear Ms. Brown:

We have received your payment in the amount of \$7,312.83 for the above referenced parcel. However, the payment was \$353.21 short.

Since this property has delinquencies dating back to 2005 or prior it has been certified to the upcoming Tax Sale scheduled for May 27, 2010. Attached is a Statement of Delinquent Taxes Due computed to May 27, 2010 for your convenience. Please be advised the balance owing must be paid in full by cash or by official ("certified") bank check before May 27, 2010 to avoid the Tax Sale.

Should you require further assistance, please contact the Collections Division at 801-468-3404.

Sincerely,

Bonnie Salt Lake County Treasurer's Office

lh:C29tsshort Enclosure



SALT LAKE COUNTY TREASURER

LARRY W. RICHARDSON
SALT LAKE COUNTY TREASURER

Anna F. Gallagher Deputy County Treasurer

BENJAMIN I. UMEADI ACCOUNTING DIRECTOR

JOHN N. NELSON COLLECTIONS DIRECTOR

SALT LAKE COUNTY
GOVERNMENT CENTER
2001 SOUTH STATE STREET
SUITE N-1200
SALT LAKE CITY
UTAH 84190-1250
PHONE (801) 468-3400
FAX (801) 468-3156

11-24 1210(8) OFFICIAL CHECK

0603212255

Operator I.D.: utah2064

March 19, 2010

PAY TO THE ORDER OF

SALT LAKE COUNTY TREASURER ***RE: #16-07-229-009-0000235***

One thousand two hundred forty dollars and 75 cents

****\$1,240.75****

VOID IF OVER US \$ 1,240.75

WELLS FARGO & COMPANY ISSUER

420 MONTGOMERY STREET SAN FRANCISCO, CA 94163 PAYABLE AT WELLS FARGO BANK, N.A. FOR INQUIRIES CALL (480) 394-3122

> 505626II #O603212255# ###21000248#4861

APP Form 3 (12/03)

SALT LAKE COUNTY

Make Checks Payable To:

SALT LAKE COUNTY TREASURER

P. O. Box 410418

IMPORTANT! PLEASE READ!

- CASH MAILED AT TAXPAYER'S RISK, COUPON MUST ACCEMPANY

. PLEASE PRINT PARCEL NUMBER(S) ON YOUR CHECK,

- YOUR CANCELLED CHECK IS YOUR RECEIPT.

84141-0418 SLC, UT

2010 TAX SALE

16-07-229-009-0000

235

DELINOUENT PAYMENT 1,240.75

AMOUNT ENCLOSED

REQUEST FOR CHANGE OF MAILING ADDRESS

NAME

ADDRESS

CITY & STATE

ZIP CODE

PHONE #

I certify that I am entitled to receive the property tax notice on this parcel. Any false statements or omissions are punishable under Utah law by a fine and/or imprisonment.

Security Features Included.

BROWN, SUSAN A PO BOX 18488 SALT LAKE CITY

84118-0488

160168700A

1329 2010 0020 0235 1607229009000000 00000124075 9

19 MAR MILLEPHI



SALT LAKE COUNTY TREASURER 2001 S STATE ST #N1200 SALT LAKE CITY UT 84190-1250





K. WAYNE CUSHING SALT LAKE COUNTY TREASURER

THE SALT LAKE COUNTY TREASURER'S OFFICE IS LOCATED IN ROOM N 1200, IN THE NORTH BUILDING OF THE COUNTY GOVERNMENT CENTER AT 2001 SOUTH STATE STREET. OFFICE HOURS ARE 8:00 A.M. TO 5:00 P.M. OUR TELEPHONE NUMBER IS 801-468-3400.

ADDINESS OF PROPERTY

729 S 500 E

MANIL ITO

AA 3916-13-9

#8WNBNKS# #160722900900001#

SUSAN A BROWN PO BOX 18488

SALT LAKE CITY UT 84118-0488

CERTIFICATION BILLING

IMPORTANT NOTICE

THIS CERTIFICATION BILLING
IS FOR UNPAID MUNICIPAL-TYPE
SERVICES WHICH HAVE BEEN
CERTIFIED TO THE COUNTY
TREASURER BY THE
SERVICE PROVIDERS LISTED
BELOW. UNPAID CERTIFICATIONS
ARE A LIEN ON THE PROPERTY ON
A PARITY WITH GENERAL TAXES.

) krageliege:	(6/A)F (6(0)D)E	DES(ME)[2](O)	V DATE TAX.	, , , , , , , , , , , , , , , , , , ,		FLPENALT/IES VITERIEST	SUETOTAL
distribution of party and	13		C WEED/DEBRIS	12/06/2010	1,534.80	0.00	0.00	1,534.80

TOTAL CERTIFIED AN	TOUNT	1,534.80
ADDITIONAL	RETURNED CHECK FEE	0.00
CHARGES	ADMINISTRATIVE FEE	0.00
	TOTAL DUE	1,534.80

OFFICIAL NOTICES CONCERNING THIS PROPERTY

AMOUNTS CERTIFIED BY SPECIAL DISTRICTS MAY BE APPEALED ONLY TO THE DISTRICTS. REFER TO THE LIST OF CERTIFYING DISTRICTS ON THE BACK OF THIS BILLING.



A. MAYNE CUSHING SALT LAKE COUNTY TREASURER

SALT LAKE COUNTY GOVERNMENT CENTER 2001 SOUTH STATE STREET #N1200 P.O. BOX 410418 SALT LAKE CITY, UTAH 84141-0418

OFFICE HOURS ARE 8:00 A.M. TO 5:00 P.M. FELEPHONE: (801) 468-3400 EMAIL: SLCOTREASURER@SLCO.ORG

729 S 500 E

******************AUTO**5-DIGIT 84118

AA 11294_P53 T32

#BWNBNKS# #160722900900001#

FARMETERS XAT TARUDALLE C

THIS DELINGUENT TAX STATEMENT IS FOR

ALL DELINQUENT TAXES

TOGETHER WITH RELATED PENALTIES, FEES, AND INTEREST ACCRUED THROUG!

MARCH 31, 2011

PAYMENTS MADE OF POSTMARKED AFTER THE ABOVE DATE ARE SUBJECT TO ADDITIONAL PENALTY AND INTEREST CHARGES.

13	202	GENERAL PROPERTY	1,311.66	32.79	22.95	1,367.40
- 12		SLC WEED/DEBRIS	1,629.00	40.73		1,698.23
10	200	OLO MELDIDEDITO	1,023.00	40.75	20,50	

FAY TAKES ONLINE AT:
VANW.TREASURER.SLCO.ORG
YOUR PIN IS:

YYBESIU

TOTAL TAX, PENALTIES AND INTEREST

ADDITIONAL RETURNED CHECK FEE 0.00

CHARGES ADMINISTRATIVE FEE 0.00

TOTAL DUE ON OR BEFORE 03/31/2011

3,065.63

PAY BY 03/31/11 TO AVOID ADDITIONAL INTEREST CHARGES.



202

13

LARMY W. RICHARDS ON SAUT LAKE COUNTY TREASURER

SALT LAKE COUNTY GOVERNMENT CENTER 2001 SOUTH STATE STREET #N1200

OFFICE HOURS ARE 3:00 A.M. TO 5:00 P.M.

TELEPHONE. (801) 468-3400 EMAIL. SLCOTREASURER @ SLCO ORG WWW.TREASURER.SLCO.ORG

729 S 500 E

*****************AUTO**5-DIGIT 84118

AA 8225_P45 T25

3,732.96

#BWNBNKS# #160722900900001#

Haladahalladladdaalalladdahaladahald

GENERAL PROPERTY

Susan A Brown PO Box 18488

Salt Lake City UT 84118-0488

DELINGUENT TAX STATEMENT

WEGETALLROHEL

THIS DELINQUENT TAX STATEMENT IS FOR:

ALL DELINQUENT BALANCES

TOGETHER WITH RELATED PENALTIES, FEES, AND INTEREST ACCRUED THROUGH

AUGUST 31, 2009

PAYMENTS MADE OR POSTMARKED AFTER THE ABOVE DATE ARE SUBJECT TO ADDITIONAL INTEREST CHARGES.

850.22

4,657.84

4,657,84

Park in the same that the religion of the same same

74.66

			The second secon
			ţ
and the second s	AND THE SECOND STREET,		
PAY TAXES ONLINE AT:	TOTAL TAX, F	PENALTIES AND INTEREST	4,657.84
YOUR PINIS:	ADDITIONAL	RETURNED CHECK FEE	0.00
BEE PAYMENT OPTIONS ON BACK	CHARGES	ADMINISTRATIVE FEE	0.00

OFFICER STREETS ON GERMAN SERVICE STREETS OF THE

IF ANY DELINQUENT BALANCE REMAINS ON 03/15/10 THIS PARCEL WILL BE SUBJECT TO FINAL TAX SALE ON 05/27/10. ALSO AN ADMINISTRATIVE FEE OF \$250 AND ADDITIONAL INTEREST WILL BE CHARGED. PAY BY 08/31/09 TO AVOID ADDITIONAL INTEREST CHARGES.

TOTAL DUE ON OR BEFORE 08/31/2009

PLEASE REVIEW THE IMPORTANT INFORMATION ON THE BACK OF THIS STATEMENT.



MBY I.A. MCELLAS IN AKE COUNTY TALAS IALA SALT LAKE COUNTY GOVERNMENT CENTER 2001 SOUTH STATE STREET #N1200

OFFICE HOURS ARE 8:00 A.M. TO 5:00 P.M.

TELEPHONE. (801) 468-3400 EMAIL: SLCOTREASURER @SLCO.ORG WWW.TREASURER.SLCO.ORG

729 S 500 E

AC 17103-GRP 1-TRAY, 56 *********AUTO 5-DIGIT 84118

#BWNBNKS# #160722900900001#

SUSAN A BROWN PO BOX 18488 **SALT LAKE CITY UT 84118-0488**

DIRENTENE XX TRATEMENT

THIS DELINQUENT TAX STATEMENT IS FOR:

ALL DELINQUENT BALANCES

TOGETHER WITH RELATED PENALTIES, FEES, AND INTEREST ACCRUED THROUGH

JANUARY 15, 2009

PAYMENTS MAJE OH POSTMARKED AFTER THE ABOVE DATE ARE SUBJECT TO ADDITIONAL INTEREST CHARGES.

 $G(X) = \{(1) \otimes (1) \}$ 0.00 --- 903.08 885.37 102 GENERAL PROPERTY

PAY TAXES ONLINE AT: WWW.ATREASUAER.SLCO.ORG YOUR PIN IS:

YYBESIK REPAYMENT OPTIONS DA BACK

TOTAL TAX, PENALTIES AND INTEREST ...ADOITION.A... RETURNED CHECK FEE

ADMINISTRATIVE FEE TOTAL DUE ON OR BEFORE 01/15/2009

903,08

903.08

0.00

TRUNG THIS PROPERTY

THE TOTAL DUE IS FOR 2008 ONLY. PAY ON OR BEFORE 01/15/2009 TO AVOID ADDITIONAL CHARGES. UNPAID PRIOR YEAR CHARGES ON THIS PARCEL AS OF 01/15/2009 = \$3,525.12.

CHARGES



LARRY W. RICHARDSON SALT LAKE COUNTY TREASURER

SALT LAKE COUNTY GOVERNMENT CENTER 2001 SOUTH STATE STREET #N1200

OFFICE HOURS ARE 8:00, A.M. TO 5:00 P.M.

TELEPHONE: (801) 468-3400 EMAIL: SLCOTREASURER@SLCO.ORG • WWW.TREASURER.SLCO.ORG

_10)0)c(=(5)c(0)g0(c(0)g1(c(0)g0(c)

729 S 500 E

MANLITE

**********AUTO 5-DIGIT 84118

AC 6865-GRP 1-TRAY 26

#BWNBNKS# #160722900900001#

BROWN, SUSAN A PO BOX 18488

SALT LAKE CITY UT 84118-0488

DELINQUENT TAX STATEMENT

Elaire Marky are to the same

THIS DELINQUENT TAX STATEMENT IS FOR:

ALL DELINQUENT BALANCES

TOGETHER WITH RELATED PENALTIES, FEES, AND INTEREST ACCRUED THROUGH

JUNE 30, 2008

PAYMENTS MADE OR POSTMARKED AFTER THE ABOVE DATE ARE SUBJECT TO ADDITIONAL INTEREST CHARGES.

13 202 GENERAL PROPERTY		2,847.59	56.95	annar payamistrationimali 452.80	District Control of the Control of t
Markalan na aktoria Maranda aktoria da Marka Baraha kangaran da					
					i de la compania de La compania de la co
		ng to the ballong. Managan and an analysis			
활성 1일 : 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1					
					The state of the s
			á e e e e		
	1				
PAY TAXES ONLINE AT:					
WWW.TREASURER,SLCO.ORG					
YOUR PIN IS:					
YYBESIC					
SEE ONLINE PAYMENT OPTION ON BACK.					
CREDIT CARD PAYMENTS CAN BE					
MADE ONLY ONLINE OR BY TELEPHONE.					
SEE CREDIT CARD PAYMENT					
OPTION ON BACK. 2.5% CONVENIENCE FEE CHARGED ON	TOTAL TAY F	PENALTIES AND INT	EDECT	<u> </u>	3,357.34
ALL CREDIT CARD PAYMENTS.	IVIAL IAA, I	CIANTIES MAD IMI	ENCOI		
CREDIT CARDS ARE NOT ACCEPTED AT	1100		0.00		
THE TREASURER'S OFFICE.	THE TREASURER'S OFFICE. CHARGES ADMINISTRATIVE FEE		0.00		
TC	TAL DUE ON	OR BEFORE 06/	30/2008		3,357.34

OFFICIAL NOTIGES CONGENING THIS PROPERTY

PAY BY 06/30/08 TO AVOID ADDITIONAL INTEREST CHARGES.

Treasurer of Salt Lake County, Utah Statement of Delinquent Taxes Due

Part

BROWN, SUSAN A
PO BOX 18488
SALT LAKE CITY UT 84118-0488

CERTIFIED FOR TAX SALE CASH OR CERTIFIED FUNDS REQUIRED

Payoff Date: May 27, 2010

Yr./Parcel # 09/16-07-229-009-0000

Type

235 SALT LAKE CITY WEED & DEBRIS

Property Location: 729 S 500 E

Delinquent taxes due:

YR TD Taxes Penalty Fee Rate Interest Period Interest Subtotal 09 13 1,201.40 24.03 .0625 010110-052610 30.64 1,256.07 TOTAL DUE 1,256.07

Make checks payable to:

SALT LAKE COUNTY TREASURER

2001 S. State St. N1200

Salt Lake City, UT 84190-1250

Be sure to indicate parcel number(s) on check(s). Please return this notice or a copy of this notice with your payment.

A Redemption Certificate will not be issued until all taxes, penalties, interest, and costs have been paid in full. A parcel having a delinquent tax outstanding for more than five years may be certified for TAX SALE. Properties certified for Tax Sale are charged an Administrative Fee and accrue additional interest through the day of the Tax Sale. Properties may be redeemed by paying the total amount due at any time prior to actual sale for delinquent taxes. All redemptions are accepted as paid by or on behalf of the owner of record. Another party redeeming property obtains no rights in or to the property by virtue of making the payment.

Total due is good only through the interest date shown. Interest accrues daily on the unpaid balances at the rate(s) indicated above.

Payments applied as directed may not be transferred or refunded. Payment by other than cash or certified funds and receipts or redemption certificates based thereon are conditional pending final collection of funds.

Mail statement to:
Letter # Chtsupt
Prepared by: Date: 377

Susan A. Brown 4787 Meadow Wood Way Taylovsville, Ut 84118

May , 2011

To Whom It May Concern:

Considering the proprety at 729 So. 5th E

I moved into that house in 1954. I Was 4 years old. My parents, brother, grandmother and I lived in that house untill the last one died, except I, in 2000.

My father wanted me to keep the proprety

In case any of the grandchildren needed a place

to live. In deed that was what I tried to

do. My son and wife and 3 sons moved in and

lived there for 7 years.

One to the fact the house was not insured (the insurance companies did not want to insure the house because the wiring was ancient). Indeed that was what caused the fire. On April 28,2008 there was a fire that rendered the house un fit to live in. The fire department said it was 50% destroyed. It didn't help they had to take a hotchet to the roof.

My earnest desire was to rebuild the house for my family. Two years ago my son-in-law (Eddie Allgier) Visited the historical society and talked to some of

their representives concerning what their expectations were. He also visited the zoning department about their expectations-

We came to the conclusion that considering every move would have to be approved by an building in spector the cost would make it impossiable.

Also due to the fact that the Zoning department sent building inspectors to inspect the proprety and they said the foundation had popped; under pinning would be needed the cost would be 80-90 thousand dollars.

Anyway you look at it now the proprety has to be destroyed and rebuilt.

Before the house fire in 2002 I obtained a Home Equity Loan from Beneficial Figure. I began to make home repairs to try and keep the house in good condition. We put on a new roof, and plumbing repairs ceiling repairs ect, Than the house fire in 2008 caused that the house could not be occupied

Carrently I owe \$16.153.03 to Beneficial for the Home Equity Loan, that I secured to fix up the proprety.

Since 2008 we haven't been able to keep Caught up on all the expenses on the house. House taxes, fines and pearn laties for failure to

I made the second payment on May 11, 2011. John So concerning the house figurially JAKI BURRIED. I owe over \$20,000 dollars to stay even I also have a grandson we raised on a mission in Hallifax Canada. That cost is I desperately need the permit to take down the house,
Summery
1. It is a disgrace to the peigh bor hood on 5th East, 2. Homeless people continually enter in and out of the house, discarding garbage in and out. 3- Myself and the city continually board it up only to have it forn down so the homeless people can enter it again, 4. Due to fire damages and the house's foundation popping the cost would be well over a \$100,000,000 to rebuilt. 5. My bill to Beneficialis \$16,153.63 6. My current bill to SLC is \$3065-65 7. In March of 2010 I paid \$ 1312.08. *8. We have already had two buyers extend earnest money to buy propriety ", but pulled out at the last moment due to difficulties with the city. We currently have a buyer who will team down and rebuilt according to exact plans further Concerning Home Equity Loan for 729 so. 5 East Susan A Brown.
4767 Meadow wood way
Taylors willo Ut/po Box
18488
Taylors wille
84118

March 31,204

Stephen W Whiting Cannon Law Associates

In regard to your complaint about the default of the loan. I have had the proprety up for Sale for about 3 months. One of the main reasons is to pay off my loan to Benefical.

On two different occassions I have had buyers who made offers to buy the proprety. Ernest money was offered, controcts signed. And my realtor has called your office twice to get a pay off amount.

Twice the city of Salt Lake (The Zoning Permit Dept) has made it impossiable for the buyers to continue with the sale and they have withdrawn their offers.

The problem is that the proproty is in the historical district (on the East side of 5th f and 7.5. - 729 5 5 E).

App. 5 years ago the house suffered a fire that the SEC Fire Department said destroyed 50% of the proprety. We were unable to get insurance for the proprety due to the fact the wiving was old and indeed that is what caused the fire-

During one of the offers to purchase the proprety - officals from the zoning department sent building inspectors to inspect the proprety and they said the foundation had popped, under pinning that would cost so-as thousand dollars would be needed to

not rebuild they would have to destroy the proprety and then rebuild.

But the SLC Zoning Committee said even it Someone purchased the proprety they will have to wait a year before they can apply for a permit to tear down the existing house.
The second buyer -who was a general contractor officially with drew his offer. But is still interested.

We have a 3th buyer who has offered an intention to purchase and put down evnest money and signed contracts oul is waiting-

I have a Realtor who wants to talk with You. Who can give you move detailed information. Her name is Sam - phone no# 801-635-0422.

A year ago my husband and I paid \$8,000,00 in fines and proprety taxes to try and keep the house and restore it. We realize that isn't going to work.

My realton feels that I stand the bost chance to obtain a permit to tear down the proprety because I have owned the proprety since my Eather died.

My realtor is preparing a case to present to the Zoning committee (there are 10 factors they use to consider whether or not to grant the permit. One is that it is a hardship to the owner.)

Please give us some time to do this. They make

it very difficult. *If I can make payments to show intent. I will

AATT; Law yens accepted my payment request. I have made 2 payments. April 29,2011 and May 11,2011 total 900,00

Susau A Brown April 10, 2011

P.O. BOX 8873 VIRGINIA BEACH, VA 23450-8873



Home Equity Loan

SUSAN BROWN 4787 MEADOW WOOD WAY, KEARNS, UT 84118-2844 02/20/11

1- 800.395-5323 Nicole Moon

Account #: 91170500613946

Dear SUSAN BROWN:

This letter is to inform you that the above referenced account is being serviced by our Recovery Processing Center. You may contact us at the following address:

BENEFICIAL PO Box 8873 Virginia Beach, VA 23450

Due to the delinquency of your loan, we have accelerated the entire balance due upon your loan dated 20010625. The balance due is \$16,153.03

If you have questions, please contact us at 1-800-477-7095 during normal business hours.

Sincerely,

BENEFICIAL Recovery Processing Center

THIS IS AN ATTEMPT TO COLLECT A DEBT BY A DEBT COLLECTOR AND ANY INFORMATION OBTAINED WILL BE USED FOR THAT PURPOSE.

PLEASE NOTE THIS STATEMENT DOES NOT APPLY TO YOU IF YOU FILED A BANKRUPTCY PETITION AND RECEIVED A DISCHARGE OF YOUR PERSONAL LIABILITY FOR THE OBLIGATION IDENTIFIED IN THIS LETTER OR THERE IS AN AUTOMATIC STAY CURRENTLY IN EFFECT. IN EITHER CASE WE MAY NOT AND DO NOT INTEND TO PURSUE COLLECTION OF THE OBLIGATION FROM YOU PERSONALLY AND THIS LETTER IS NOT INTENDED AS A DEMAND FROM YOU PERSONALLY. UNLESS THE BANKRUPTCY COURT HAS ORDERED OTHERWISE, HOWEVER, PLEASE ALSO NOTE THAT DESPITE ANY SUCH BANKRUPTCY, BENEFICIAL RETAINS A SECURITY INTEREST IN THE PROPERTY IDENTIFIED IN THIS LETTER, WHICH BENEFICIAL MAY PURSUE AND ENFORCE.

Esta carta contiene informacion importante sobre su cuenta y podria requerir su atencion. Si tiene alguna pregunta y desea hablar en Espanol con un empleado, sirvase comunicarse con nosotros al 1-800-477-7095, marque el numero 2, durante nuestras horas de oficina normales.

91170500613946

Susah 40-205-2890

174

Date:	Time:
Residence/Business	
Server Name:	
Served Upon:	

THIS IS A TEN-DAY SUMMONS, PLEASE RETURN IMMEDIATELY PON SERVING

STEPHEN W. WHITING #11828 CANNON LAW ASSOCIATES Attorney for Creditor 8619 S. Sandy Pkwy., Ste. 111

Sandy, UT 84070

Telephone: (801) 255-7475 Facsimile: (801) 255-7526 File Reference No. 2110118

DATE	98211	771	~=14 <u>0</u>	THE PARTY OF THE P
(M/B	7	187	magan	my from
1.000581	Bunk	MA	PERSON)
COMSTA	DLE REITZ,	SALL	YKE COU!	ety, Utah
DEPUTY	-	<u>4</u> A		253-5468

THIRD DISTRICT COURT, STATE OF UTAH

SALT LAKE COUNTY, WEST JORDAN DEPARTMENT

BENEFICIAL MORTGAGE CO. OF	
UTAH	SUMMONS
Plaintiff,	
VS.	
	Civil No.
SUSAN BROWN	Judge
•	
Defendant.	

THE STATE OF UTAH TO THE ABOVE-NAMED DEFENDANT:


You are hereby summoned and required to file with the clerk of the above entitled court at 8080 S REDWOOD RD., WEST JORDAN UT 84088 an answer in writing to Plaintiff's Complaint, and to serve upon, or mail to Bryan W. Cannon, Plaintiff's attorney, at 8619 South Sandy Parkway, Suite 111, Sandy, Utah 84070, a copy of said answer within TWENTY (20) days after the service of this summons. If you fail to do so, judgment by default will be taken against you for the relief demanded in said Complaint. Said Complaint will be on file with the Court within ten (10) days after service of this summons. Should the Complaint not be filed within ten days after service of this summons, you need not answer the Complaint. You may contact the Clerk of the Court at least thirteen (13) days after service of this summons at 801/233-9700 -3 to determine if the Complaint has been filed with the Court.

DATED this 1th day of April, 2011.

STEPHENW. WHITING

Attorney for Plaintiff

SERVE DEFENDANT AT: 4787 Meadow Wood Way Salt Lake City UT 84118





14712 So. Heritage Crest Way Bluffdale, UT 84065 p: 801-495-1830

p: 801-495-1830 f: 801-495-1833

12 July 2011 Mr. Sam Beck Windsor Real Estate

Re: 729 South 500 East

Sam.

Thank you for the inquiry about this home. I have inspected this home in the past for probable investors. I will give you the same advice I gave them.

Homes built at the time this one was *do not* have a strong enough foundation for stabilization or lifting repair. They usually have a very small footing. The foundation wall is commonly no more than 6" thick. The foundation walls are not reinforced with rebar as required by current building codes. A compounding problem with homes of this age is; after they were built a "shelf" basement was created by removing soil from under the existing structure. This practice allowed the foundation walls to "move in" at the bottom and "rotate out" at the top. This made the foundation appear to spread apart causing movement and fracturing of the un-reinforced concrete foundation.

The building at 729 South 500 East has all of these issues. In addition the water used to fight the house fire will have further softened the soil around the poor foundation compounding repair problems. The narrow lot also restricts access to the exterior side of the foundation walls (south side).

12 July 11

My recommendation is to demolish the entire structure.

Please keep in mind I am not an engineer. This opinion is based on my experience in settlement and foundation repair. Call me if you have any questions (801.420.4385).

Sincerely,

William (Bill) Boulter

Estimator/Project Manager



August 1, 2011

Ben Scribner 1866 Beaumont Cr. Salt Lake City, UT 84121

Subject: Structural Inspection of 791 S. 500 E; Salt Lake City, UT.

Dear Ben:

At your request, an inspection of the above property was performed on August 1, 2011. The report that follows has been prepared based on this inspection. This inspection was performed by and report written by Scott Bernhisel, P.E. For you information, a copy of Scott Bernhisel's resume is included.

• The house has been devastated by fire. The purpose of this inspection and report is to evaluate the condition of the structure and to determine what rehabilitation efforts, repairs, and/or replacement will be needed in its reconstruction.

This inspection report is limited to observations made from visual evidence. No destructive or invasive testing was performed. The report is not to be considered a guarantee of condition and no warranty is implied.

Based on our review of the property, we do advise against any attempt to restore, rebuild or refurbish the house. Though it is "quaint" and originally constructed with somewhat of the character of its era, it departs too significantly from what will be required during a remodeling of this magnitude. Also, should remodeling be done, there may be lasting and latent defects related to its decomposing condition that can not be economically removed.

There are serious problems with structural systems of this building that make repairs financially unwise. Much of the structure has been lost, and portions that do remain do not meet the requirements of modern building codes, to which the building will be held.

DESCRIPTION

The basic construction of this home is a bungalow style, single story building with narrow basement and an upstairs loft area. The exterior walls are constructed with unreinforced brick. For purposes of this report, the building is assumed to face west. Additional directions (left, right, rear, etc.) are taken from the view point of an observer standing in front of the building and facing it. It is presumed to be about 90 years old.

STRUCTURAL

Observations and Recommendations

The basic construction of this building consists of a concrete slab on grade basement floor with perimeter concrete foundation walls extending up to support the main floor framing. The foundation walls are approximately 7' high around the perimeter.

- The height of the basement is too low for modern clearances of 6' 8".
- Windows from the basement do not provide egress requirements and will need to be cut to six square feet of net opening.
- The foundation has cracked and moved outward. Excavation around the foundation will be needed to repair the damage, seal the wall against water seepage, and cable tie it together.
- Such movement in the foundation implies that the concrete is NOT reinforced.
- Toward the front south corner, there is no foundation.

The perimeter walls consist of two wythes of brick. In this case, the brick is not a veneer, but is the primary load carrying member. Experience with buildings of this type (unreinforced masonry) and period generally imply that the building is not tied together to resist large dynamic lateral forces, such as those created by a high magnitude, long duration earthquake.

- There is no connectivity of the floor joists to the wall. They are simply inserted between masonry pockets.
- Floor joists were burned in several areas. Exposure to moisture will likely cause long term rot conditions in the open end grain of the joists.
- The south wall has rotated outward as it is supported on the foundation which has also rotated outward. This is no longer plumb, and its condition is compromised.

The roof structure consists of 2x4 stick framed rafters. Rafters spanning over the front porch are cracked and failing.

- Similar to the floor joists, the roof rafters lack any positive connection between the rafters and ceiling joists, and also to the wall.
- Without positive anchoring to the rafters, the unreinforced wall is at risk of failing during an earthquake.
- The wall can not be reinforced as there are no voids in which to install steel and concrete. The brick is solid masonry without any voids.

- Code requirements for reconstruction should insist on installing a new interior wood frame wall to support the roof. This will reduce the overall interior of the house dimensions.
- There is no insulation for the walls. Model energy codes, which will be required during this reconstruction, need R13, which corresponds to 3½ wall framing.

The upstairs roof is vaulted with interior ceiling finishes are secured directly to the underside of the roof rafters.

• This does not allow for insulation. Model energy standards require R38 insulation in the attic. This will require a 2x10 sized rafter to provide the sufficient depth to insulate. The present rafters are only 2x4.

The stairs to/from both upstairs and the "basement" are excessively steep and narrow. Any remodeling will require the stairs meet modern safety standards, with a width not less than 36 inches; continuous head room a minimum of 80 inches; and stair riser heights 7 inch maximum with tread depths of 11 inches minimum.

• The stair requirements alone will requirement major renovation and reduction of interior usable space.

Environmental Concerns.

Conditions inside the house raise obvious concerns that illegal activities have been engaged in.
These could include but not limited to; use or manufacture of illegal substances or presence of
substances banned or controlled by federal, state or local law.

Based on visible evidence, we consider the **structural condition** of this building to be forfeit and not a candidate for remodeling. There are too many concerns that can not be engineered to meet modern safety standards.

Many things have been discussed in this report. However, we realize that there may still be other things of interest to you that have not been discussed. Therefore, we encourage you to call with any additional questions you may have. Thank you for the opportunity to be of assistance to you.

Sincerely,

Criterium-Bernhisel Engineers, Inc.

Scott Bernhisel, P.E.

SCOTT M. BERNHISEL, P.E.

EDUCATION and LICENSURE:

Master of Business Administration, 1991, University of Utah

Civil Engineering; Bachelor of Science, 1986, University of Utah

Professional Engineer, State of Utah, Reference number 173662

Associate of Arts - Architecture, 1981, Utah Technical College

EXPERIENCE:

Criterium - Bernhisel Engineers:

93 - Present

Owner & managing engineer for residential and commercial building inspections, seismic & structural upgrade, project management services, scheduling, estimating.

Kennecott Corporation: Plant Projects Group

7/93 - 6/95

Project / structural engineer for environmental remediation and major project facilities improvement; regulatory compliance, underground reclamation.

Kennecott / Flambeau Mining Co.

Ladysmith, WI 8/92 - 7/93

Project Engineer for construction of open pit mining facilities including a contaminated water collection system and treatment plant, administration building and laboratory, and railroad spur.

Kennecott Corporation: Tailings Modernization

3/90 - 8/92

Project Engineer / Analyst for long-range planning of mine tailings disposal alternatives.

Buehner Corporation

Salt Lake City, UT 3/86 - 1/90

Technical Sales / Marketing and engineering of precast concrete building products.

Conesco Inc.

Salt Lake City, UT 1980 - 1986

Designer / Engineer of concrete forming and shoring system for residential, industrial and mining projects.

AFFILIATION

- · National Academy of Building Inspection Engineers; NABIE
- · American Society of Civil Engineers; ASCE
- · International Conference of Building Officials; ICBO

SKILLS & INTERESTS

- · Well versed in all phases of Engineering, Construction, and Building Technology.
- · Familiar with electrical, instrumentation, mechanical, geotechnical, hydraulics, piping, and hydrology.

Ben Scribner 7525 Prospector Drive Salt Lake City, UT 84121 801.381.3595

October 7, 2011

Re: 729 South 500 East

To whom it may concern:

I am writing this letter to recommend that the City of Salt Lake, the Historical Society, and any other agencies involved in planning and zoning for the above referenced property allow this home to be demolished and a new home be built on the lot in its place. It is not economically feasible to repair or restore the home that is standing.

As you may be aware, the structure currently occupying this space is in a horrible state of disrepair. It is a haven to squatters, and I can only imagine is a threat to the safety and health of the neighborhood. While at first I examined this property to rebuild and restore the existing structure, after careful analysis by engineers and other professionals, the only remedy that makes sense is a complete tear down. I am recommending that a new single family home be built, of a modern, contemporary design, reflecting the demand of the evolving urban style. Furthermore, as it stands there is no parking on the property which limits the marketing potential and value. The new construction would allow for off-street parking incorporated in such a way that it will not compromise the curb appeal or take away from the overall design.

I have attached multiple reports from the engineers and others who have determined the property is a hazard, who have also concluded it is not conducive to repair and restoration. While I would have loved to restore the property in a way that would retain the style of the classic bungalow, as that is impossible I have spent hours researching and designing a new home that would be a solid improvement to the community.

Please feel free to call me should you have any questions or need anything further.

Respectfully,

Ben Scribner

Gmail - FW: 729 s 500 e



Sam Beck <stbeckre@gmail.com>

FW: 729 s 500 e

1 message

ben scribner <3813595@gmail.com>

To: "stbeckre@gmail.com" <stbeckre@gmail.com>

Wed, Oct 26, 2011 at 5:14 PM

Sent from my Windows Phone

From: Jeremy Bitner

Sent: Wednesday, October 26, 2011 1:20 PM

To: <u>3813595@gmail.com</u> **Subject:** RE: 729 s 500 e

To Whom it May Concern:

In my professional opinion the home located at 729 S. 500 E. is a hazard and should be torn down. I have inspected the property and have many concerns about the financial implications to try and rebuild the structure. The entire roof structure is gone from the fire damage. The porch has settled so much that it cannot be repaired without removing it. The exterior walls are bowed. The foundation needs to be shored up. The floor joists are insufficient to carry the required load. The attic living space cannot be recreated without new stairs that pass code, new exterior bearing walls, and new roof trusses. All of the electrical, HVAC, and plumbing have been destroyed or would not pass inspection. If we follow the current building codes and engineering guidelines, it will be much, much cheaper to tear down and rebuild another more attractive house than it would be to try and salavage the damaged "shell" that is there now.

In summary, the structure is by far more of a liability than an asset to the homeowner and the city. Someone is going to get hurt if the house is not torn down and left in its' current state.

Best Regards,

Jeremy Bitner
Bitner Excavating LLC
Ivy League Homes, Inc.
Equity Real Estate - Professionals
cell (801) 792-9292
fax (801) 571-6376

Date: Tue, 25 Oct 2011 17:02:39 -0600

Subject: 729 s 500 e

From: 3813595@gmail.com
To: jeremybitner@hotmail.com

Spencer Passey <passpe@wfrmls.com>

To: Sam Beck <stbeckre@gmail.com>

Sam,

I am so disappointed that your listing on 500 E has not sold. My client is still interested in the property, but only as a tear down. They had Helical Pier engineering give them an estimate of over \$40,000 just to sure up the foundation. Due to these extreme costs of preservation which would add no value, the buyer had looked seriously at a tear down situation. After a visit to the City of Salt Lake and being told it would be nearly impossible to get at tear down permit the buyer decided it wasn't worth the effort especially since the home is on a busy street with no off street parking. My client may still be interested at \$20,000 if your seller can get a tear down permit. We are headed into winter and the costs and duration of the project will cost extra.

Best of Luck,

Spencer Passey, ABR **RE/MAX Associates** 6629 S 1300 E SLC, UT 84121 801-566-4411 o 801-566-0530 **f** 801-580-7170 m passpe@wfrmls.com [Quoted text hidden]

Sam Beck <stbeckre@gmail.com>

To: Darrell.scharman@gmail.com

Hi Darrell

Here is the email from the other agent.

Thanks soooo much!

Sam

[Quoted text hidden]

Tue, Nov 1, 2011 at 4:18 PM

Thu, Oct 27, 2011 at 2:46 PM

Greg Cleverly <greg@myutahhomeguide.com>
To: Sam Beck <stbeckre@gmail.com>

Tue, Nov 1, 2011 at 5:24 PM

Sam

I am glad to give feed back on this property and the circumstances around a purchase. Having dealt with close to 200 rehab properties over the last 10 years, I have a lot of experience. First with how my buyer was treated by the city, and I am sure other potential buyers have faced as well. Investors are willing to put their money at risk only when they can determine the actual risk. City employees did not help eliminate risk during due diligence but instead increased it. So the uncertainty from the city increases risk and therefore must be reflected in the price. My buyer backed away at \$45,000 because at that price, the risk was still too great. He was willing to pay that price if he could keep the structure in place and pull permits and do most of the work himself as the owner. For some one to purchase and tear down the structure and build a new structure, the value would depend on what could be built in its place, given the set backs, parking requirements etc. Again, lots of uncertainty and therefore a much much lower price - I am estimating in the mid \$20s

Good luck!


Greg Cleverly
Century 21 - Everest Realty Group
[Quoted text hidden]

https://mail.google.com/mail/?ui=2&ik=86a3ee19b4&view=pt&cat=Susan%20Brown&sear... 1/5/2012

Attachment C

Photos



































Allaciiiileiil D	Attac	hment l	D
------------------	-------	---------	---

Elevations for Proposed Building



Scale 1/8" = 1' on 11" × 17"

