

Staff Report

PLANNING DIVISION

DEPARTMENT of COMMUNITY and NEIGHBORHOODS

To: Salt Lake City Historic Landmark Commission

From: Grant Amann, Principal Planner, grant.amann@slcgov.com, 801-535-6171

Date: February 1, 2024

Re: PLNHLC2022-01202 – Window Replacement Minor Alteration

Minor Alteration - Enforcement

PROPERTY ADDRESS: 182 North N St

PARCEL ID: 09-32-335-002-0000

HISTORIC DISTRICT: Avenues Local Historic District

MASTER PLAN: Avenues Master Plan

ZONING DISTRICT: SR-1A

REQUEST:

Rodrigo Schmeil and Jason Bresley, property owners, are requesting a Certificate of Appropriateness for the replacement of 18 windows. This alteration to the exterior of the home requires approval by the Historic Landmark Commission. The proposed windows, which replaced historic windows located on the North, East, and South façades of the house, would be approved retroactively as the windows have already been installed. The subject property is located at 182 North N Street and is a contributing structure within the Avenues Local Historic District. The subject property is located in the SR-1A (Special Development Pattern Residential) zoning district.

RECOMMENDATION:

As outlined in the analysis and findings in this staff report, it is Planning Staff's opinion that the requested replacement of all 18 windows generally meets the applicable standards of approval and staff recommends the Historic Landmark Commission approve the request.

ATTACHMENTS:

- A. ATTACHMENT A: Vicinity Map
- **B.** ATTACHMENT B: Applicant Materials
- C. ATTACHMENT C: Property and Vicinity Photos
- D. ATTACHMENT D: Historic Survey Information
- E. ATTACHMENT E: Analysis of Standards for Minor Alterations in a Historic District
- F. ATTACHMENT F: Applicable Design Guidelines

BACKGROUND

The property located at 182 N Street is a triplex located in the Avenues. The home was built in 1898 and is considered a contributing structure in the Avenues Local Historic District. The applicants and owners, Rodrigo Schmeil and Jason Bresley, purchased the structure in April of 2019. After purchasing, the owners performed several alterations to the building in 2020, including replacement of the windows on the north, south and east elevations and painting of the exterior without a Certificate of Appropriateness and building permit. The building was placed under civil enforcement in 2022, when it came to light that the alterations had not received a Certificate of Appropriateness authorizing the work. This application is necessary to rectify the enforcement case.

PROPERTY DESCRIPTION AND CONTEXT

History of the Property

182 N N St. was built ca. 1898 and is considered Victorian eclectic. The Structure/Site Information Form was written in 1979 and it documents the following about the house:

This two-story Victorian home is composed of a main hip roofed block and a projecting gabled

front bay. The gable clapboard has siding and returns, and simple a wooden cornice runs under the eaves around the house. The bay is rectangular on the second story, and segmental on the first. Walls of the house are finished in tongue-and-"novelty" groove siding. A window above the front door has been boarded up, and the original front porch



Subject Property in May of 1977

has been replaced with a small canopy.

The Victorian Style, materials and massing of this home contribute to the architectural character of the Avenues. The house was built ca. 1898 as an investment property for Carl O. Johnson. He owned the Salt Lake Monument Company, which still serves as a gravestone maker for the cemetery, next door at 186 N Street. Johnson lived at and operated his business at 186 N street, until about 1915 when he moved his residence from it to this house at 182 N St. He lived in the house until his death in 1940, when ownership passed to his son, Gus H. Johnson. Gus lived in the house until 1945, then sold it to Leslie Simmonds. A year later,

Simmonds sold it to Robert J. Lien. According to Salt Lake City Directories, he was a superintendent at Cudahay Packing Company. In 1949, Lien sold it to W. G. Howell.

In the years since 1949, the structure has had a few minor alterations. The largest alteration was a conversion from a single-family unit to a 3-unit multi-family structure. According to a 2003 report, the triplex conversion possibly occurred in 1953, with the addition of the "sleeping room + two bathrooms." This 2003 document also confirms the existence of 3 approved hard surface parking stalls.

The County Assessor's file indicates that previous screened porches were changed to "household area" in 1953. It is believed that this is when the conversion to a triplex took place.

Location in Context

The subject property is located near the corner of N St. and 4th Ave, which is the pedestrian entrance to the Salt Lake City Cemetery. Directly North, neighboring the property and in between the property and the cemetery is Salt Lake Monument, a headstone crafter for the cemetery. Due to the small scale of the Salt Lake Monument building and the inclined grade, the secondary elevations (north and south) are both readily visible from the public way.

DESCRIPTION OF ALTERATION

The property owners replaced all windows on the north, east, and south elevations of the structure, totaling 18 windows. The windows on the west elevation (primary/street facing) were not replaced. The prior windows were wood and original to the structure. The replacement windows are vinyl in material. According to the applicant, the previous windows were painted shut and considered "inefficient" due to the single pane. None of the window openings were enlarged or modified.



Western (Front) Elevation

The windows on the west/primary street facing elevation are original to the structure. The applicant is not seeking replacement of any windows on this elevation.



Eastern (Rear) Elevation

The applicant has replaced 5 windows on the rear addition of the structure. This elevation is not visible from the public way and the alterations took place on a non-historic addition.



Northern Elevation

The applicant replaced 6 windows on this elevation, which is readily visible from the public way. The applicant did not modify any openings or alter the style of the window. While these windows are readily visible from the public way, staff finds that they are not character defining due to the interior location of this secondary elevation.



Southern Elevation

The applicant replaced 7 windows on this elevation, which is readily visible from the public way. The applicant did not modify any openings or alter the style of the window. While these windows are readily visible from the public way, staff finds that they are not character defining due to the interior location of this secondary elevation.



KEY CONSIDERATIONS

Section 21A.34.020(G) outlines the standards which need to be met for the issuance of a Certificate of Appropriateness for the alteration of a contributing structure in a local historic district. These standards have also been listed and evaluated in Attachment E.

- 1. Appropriate Replacement Windows
- 2. Alterations to Secondary Elevations
- 3. Minor Alteration and Building Permit Process

Consideration 1: Appropriate Replacement Windows

Staff evaluates window replacements on elevations visible from the public way on a case-by-case basis. If an original window is considered to be beyond repair, staff will work with a property owner on an appropriate replacement window. Replacement considerations include the design, profile of the sash, size and proportion of the opening, as well as the material. Because this Certificate of Appropriateness is being sought after alterations were already performed, Staff was not able to evaluate the original windows.

The replacement windows installed on the subject property generally meet these considerations. While vinyl in material, the windows did not modify the opening and were recessed in a fashion to comply with the historic nature of the property.

Consideration 2: Alterations to Secondary Elevations

Features designed to be visible from the public way are generally considered character defining. While these windows are visible from the public way, they were not designed to be character defining. The windows are primarily visible due to the low scale of the structure to the north and the steep grade from the south. With that said, staff applies flexibility to alterations located on secondary elevations. After careful and professional analysis, Staff is of the opinion that the replacement windows are acceptable based on the location and relief of the windows. These side windows, although visible from the right of way, are not as significant with this architectural type. As quoted in the *Preservation Handbook for Historic Residential Properties & Districts in Salt Lake City*,

"[In determining the window's architectural significance,] typically, windows on the front of the building, and on sides designed to be visible from the street, are key character-defining elements. A window in an obscure location, or on the rear of a structure, may not be. Greater flexibility in the treatment or replacement of such secondary windows may be appropriate."

Consideration 3: Minor Alteration Elevations

Section 21A.34.020.E indicates that all exterior building work should receive a Certificate of Appropriateness before alteration of the exterior. The alterations discussed in this document have already been performed.

21A.34.020.E. "Certificate Of Appropriateness Required: After the establishment of an H Historic Preservation Overlay District, or the designation of a landmark site, no alteration in the exterior appearance of a structure, site, object or work of art affecting the landmark site or a property within the H Historic Preservation Overlay District shall be made or permitted to be made unless or until the application for a certificate of appropriateness has been submitted to, and approved by, the Historic Landmark Commission, or administratively by the Planning Director, as applicable, pursuant to subsection F of this section. Certificates of appropriateness shall be required for: 6. Alterations to windows and doors, including replacement or changes in fenestration patterns."

Because this Certificate of Appropriateness is sought after alterations were already performed, several key factors of the analysis that would have occurred are lost, namely the original historic windows. Had the City been given an application prior to the removal of windows, staff could have worked with the applicant potentially rehabilitating the existing windows.

Performing alterations without a required permit or certificate of appropriateness is prohibited and measures should be taken to ensure that alterations are being made to preserve existing historic features and materials. For example, when windows need repair in the future, it is important for the

owner and applicant to prioritize repair over replacement. Staff evaluated the windows on the front façade and determined that the windows possess a considerable degree of durability and are expected to endure for an extended period with proper maintenance. These character defining features should be restored and repaired to maintain their historical character. By requesting a certificate of appropriateness before alterations, staff can ensure that these windows are restored properly according to required guidelines.

STAFF DISCUSSION

Staff generally encourage repair over replacement of existing historic windows, the windows on these two elevations are lost and have been replaced. The replacement windows are considered acceptable due to the installation which preserves the historic profile. The important factors in installation that were maintained include the original window style, window opening and approximate recession. With that said, the original windows on the primary elevation are considered character defining and will be required to remain.

COMMISSION AUTHORITY AND NEXT STEPS

The applicant has submitted an application for a Minor Alteration in the Avenues Local Historic District. Staff does have authority to review minor alterations administratively, however, this particular application has been forwarded to the Commission due to the complexity of the proposal. The Historic Landmark Commission has decision-making authority in said matters. The Historic Landmark Commission may approve, approve with conditions, or deny the requested Minor Alteration.


Approval of the Request


If approved, the Certificate of Appropriateness will be issued for all requested windows.


Denial of the Request

If the Commission denies the proposal for replacement of the windows identified in the request, a Certificate of Appropriateness will not be issued. A new application would need to be submitted that meets the standards and guidelines to obtain a Certificate of Appropriateness in order to resolve the active enforcement case.

ATTACHMENT A: Vicinity Map








 $Property\,Aerial-South\,Looking\,North$







 $Property\,Aerial\,-West\,Looking\,East$



ATTACHMENT B: Applicant Materials

PROJECT DESCRIPTION:

The property located on 182 N Street, SLC, UT 84103 is a triplex located in the Lower Avenues. In 2019, the side and rear windows that are not visible from N street were replaced since they were non-operable due years of neglect and layers of paint, which had in effect, painted them shut. This combined with the fact that they were all single paned-windows, made the windows very inefficient and a big fire hazard to the tenants. The front façade windows (street facing) have been preserved as the original wood windows; they remain non-operable. This Minor Alteration Application is to bring the non-permitted windows that are located along the North and South elevations of the building up to regulation. The new windows match the fenestration pattern of the house, and they are not visible from the street perspective. The openings sizes are exactly as they were, the only difference is the material of vinyl and the double glazing.


Please see attached pictures and respective window dimensions.

New Windows Sizing

11ew Williams Sizing					
	NORTH ELEVATION	SOUTH ELEVATION	WEST ELEVATION		
1 ST LEVEL	- 26" x 65" (4 Windows) -	- 20" x 53" - 24" x 70" (3 Windows)	- All Original Windows		
2 ND LEVEL	- 30" x 65" - 24" x 65"	- 30" x 65" (3 Windows)	- All Original Windows		



Street View ("N" street Front of the house, original windows kept, West View)



South Elevation from N street.



North View From N street



North Elevation from Back of property.



South Elevation from back of property

ATTACHMENT C: Property and Vicinity Photos



Subject Property in May of 1977



2023 West Elevation



Northern Elevation





Southern Elevation



February 1, 2024



2023 East Elevation Rear



ATTACHMENT D: Historic Survey Information

Click here for Utah State History File – Structure/Site Information Form

Architectural Survey Data for SALT LAKE CITY Utah State Historic Preservation Office

"N" Street — Avenues Historic District (SLC Landmark District)

RLS 2007-2008, PAGE 3

Address/ Property Name	Eval./ Ht	OutB N/C	Yr.(s) Built	Materials :	Styles	Plan (Type)/ Orig. Use	Survey Year RLS/ILS/Gen	Comments/ NR Status
128 N N STREET	В	1/0 2	1955	STRIATED BRICK	POST-WWII: OTHER	OTHER APT./HOTEL MULTIPLE DWELLING	07	N04
135 N N STREET	В	0/0	1900	REGULAR BRICK STUCCO/PLASTER	VICTORIAN ECLECTIC	CENTRAL BLK W/ PROJ	07	
		1.5				SINGLE DWELLING		N04
149 N N STREET	В	0/0	1896	REGULAR BRICK SHINGLE SIDING	VICTORIAN ECLECTIC	CENTRAL BLK W/ PROJ	07	
		1.5				SINGLE DWELLING	:	N04
164 N N STREET	В	0/0	1918	REGULAR BRICK	BUNGALOW	BUNGALOW	07	
WILLIAMS, HELEN B., HOUSE		1		SHINGLE SIDING		SINGLE DWELLING	:	N04
166 N N STREET WILLIAMS, WALTER W., HOUS	B E	0/1 2	1898 c. 1940	ASBESTOS SIDING	VICTORIAN: OTHER	SIDE PASSAGE/ENTRY SINGLE DWELLING	07	N04
167 N N STREET	В	0/0	1902	DROP/NOVELTY SIDING	VICTORIAN ECLECTIC	CENTRAL BLK W/ PROJ	07	UHF EASEMENT
		1.5		SHINGLE SIDING		SINGLE DWELLING		N04
172 N N STREET	В	1/0	1906	REGULAR BRICK ROCK-FACED BRICK	VICTORIAN ECLECTIC	FOURSQUARE (BOX)	07	
JOHNSTON, HANNAH, HOUSE		2		ROCK-FACED BRICK		SINGLE DWELLING	:	N04
173 N N STREET	D	1/0	1968	BRICK:OTHER/UNDEF.	MANSARD	OTHER APT./HOTEL		VICTORIA APTS
		3		SHINGLE SIDING		MULTIPLE DWELLING		173-175 N04
181 N N STREET	В	0/1	1891	STUCCO/PLASTER SHINGLE SIDING	VICTORIAN ECLECTIC BUNGALOW	CENTRAL BLK W/ PROJ	07	
		1				SINGLE DWELLING		N04
182 N N STREET	В	1/0	1898	DROP/NOVELTY SIDING TONGUE & GROOVE	VICTORIAN: OTHER	CENTRAL BLK W/ PROJ	07	
		2				SINGLE DWELLING		N04
186 N N STREET	В	0/1	1914	CONCRETE BLOCK	PERIOD REVIVAL: OTHER	OTHER	07	SALT LAKE MONUMENT
		1		ROCK-FACED CONC. BLI	ζ.	MULTIPLE USES	:	N04

?=approximate address Evaluation Codes: A=eligible/architecturally significant B=eligible C=ineligible/altered D=ineligible/out of period U=undetermined/lack of info X=demolished

ATTACHMENT E: Analysis of Standards for Minor Alterations in a Historic District

Purpose Statement: In order to contribute to the welfare, prosperity, and education of the people of Salt Lake City, the purpose of the **H Historic Preservation Overlay District** is to:

- 1. Provide the means to protect and preserve areas of the City and individual structures and sites having historic, architectural, or cultural significance.
- 2. Encourage new development, redevelopment, and the subdivision of lots in Historic Districts that is compatible with the character of existing development of Historic Districts or individual landmarks.
- 3. Abate the destruction and demolition of historic structures.
- 4. Implement adopted plans of the city related to historic preservation.
- 5. Foster civic pride in the history of Salt Lake City.
- 6. Protect and enhance the attraction of the City's historic landmarks and districts for tourists and visitors.
- 7. Foster economic development consistent with historic preservation; and
- 8. Encourage social, economic, and environmental sustainability.

The Design Objectives and related design guidelines are referenced in the following review where they relate to the corresponding Historic Design Standards for Alteration of a Contributing Structure (21A.34.020.G).

Standard	Analysis	Finding
1. A property shall be used	The use of the property will remain the	Complies
for its historic purpose or be	same. This standard is met. This use was	
used for a purpose that	established in 1953 as a 3-unit multifamily	
requires minimal change to	building.	
the defining characteristics	No change of use is proposed.	
of the building and its site		
and environment.		

2. The historic character of	North and South Elevations (Visible	Complies
the property shall be	Windows)	1
retained and preserved. The	Windows play a crucial role in defining the	
removal of historic materials	character of historic structures by providing	
or alteration of features and	scale and contributing to the architectural	
spaces that characterize a	composition of facades. Their distinct designs	
property shall be avoided.	and fenestration patterns are integral to various	
	historic building styles. Historic windows differ	
	from contemporary ones in terms of their	
	relationship to the building's wall plane, often	
	being inset into deep openings with intricate	
	casings and sash components, casting shadows	
	that contribute to the overall facade's	
	complexity and style-defining features. With	
	that said, the replacement windows were	
	installed in a manner that preserved the historic	
	profile and opening. The loss of the historic	
	material is significant; however, these windows	
	were not considered character defining due to	
	the location on secondary elevations.	
	·	
	East Elevation (Rear Windows)	
	This elevation is not visible from the public	
	way. These windows are not considered	
	character defining due to the location on	Complies
	secondary elevation. The alterations also took	_
	place on a non-historic addition.	
3. All sites, structures and	North and South Elevations (Visible	Complies
objects shall be recognized	Windows)	
as products of their own	Staff asserts that it wasn't the intent of the	
time. Alterations that have	applicant to create a false sense of history	
no historical basis and which	with the installation of vinyl windows. While	
seek to create a false sense of	the vinyl is contemporary in material, the	
history or architecture are	installation preserves the historic profile and	
not allowed.	opening. Staff finds that the manner in which	
	the windows were installed complies with this	
	standard.	
	East Elevation (Rear Windows)	Complies
	This elevation is not visible from the public	
	way. These windows are not considered	
	character defining due to the location on a	
	secondary elevation. The alterations also took	
	place on a non-historic addition.	

4. Alterations or additions that have acquired historic significance in their own right shall be retained and preserved.	This alteration does not impact a historic alteration or addition.	NA
5. Distinctive features, finishes and construction techniques or examples of craftsmanship that characterize a historic property shall be preserved.	North and South Elevations (Visible Windows) Preserving distinctive features, finishes, and construction techniques, or examples of craftsmanship that characterize a historic property is a fundamental principle. While it is acknowledged that vinyl is notably inferior to that of wood, it is positive that the preservation of window openings remained unaffected during the replacement process. Preserving the subtle recess and profile of the windows is a favorable element. Staff has measured and confirmed this recess as a contributing factor, diminishing the visibility of the windows from the right of way. Replacement considerations include the design, profile of the sash, size and proportion of the opening, as well as the material. The replacement windows installed on the subject property generally meet these considerations.	Complies
	East Elevation (Rear Windows) These windows are not visible from the public right of way. The replacement windows comply with this standard.	Complies

6. Deteriorated architectural	North and South Elevations (Visible	Complies
features shall be repaired	Windows)	Complies
rather than replaced	The deteriorated architectural features in	
wherever feasible. In the	question, the windows, were replaced instead	
	of repaired. The new material does not match	
event replacement is	<u> </u>	
necessary, the new material	the material being replaced in composition,	
should match the material	texture, or other visual qualities. Although	
being replaced in	vinyl, the new windows did not modify the	
composition, design,	opening and are recessed in a fashion to comply	
texture, and other visual	with the historic nature of the property. The loss	
qualities. Repair or	of the historic material is significant; however,	
replacement of missing	these windows are not considered character	
architectural features	defining due to the location on secondary	
should be based on accurate	elevations.	
duplications of features,		
substantiated by historic,		
physical, or pictorial	East Elevation (Rear Windows)	Complies
evidence rather than on	These windows are not visible from the public	-
conjectural designs or the	right of way. The proposal to replace these	
availability of different	windows complies with this standard.	
architectural elements from	P	
other structures or objects.		
7. Chemical or physical	There are no chemical or physical treatments	Not
treatments, such as	associated with this proposal. This standard	Applicable
sandblasting, that cause	does not apply.	пррисави
damage to historic materials	does not apply.	
shall not be used. The		
surface cleaning of		
structures, if appropriate,		
shall be undertaken using		
the gentlest means possible.		

8. Contemporary design for alterations and additions to existing properties shall not be discouraged when such alterations and additions do not destroy significant cultural, historical, architectural, or archaeological material, and such design is compatible with the size, scale, color, material and character of the property, neighborhood, or environment.	North and South Elevations (Visible Windows) It is important to note that the choice of vinyl as the window material is contemporary, not considered durable in our city's climate, and not inherently compatible with historical contexts. Despite this, the alteration does conform to the standard due to the location and depth of the windows, along with the maintaining of the original openings, which keep the alteration from destroying the cultural and historical significance.	Complies
	East Elevation (Rear Windows) These windows are not visible from the public right of way. The proposal to replace these windows complies with this standard.	Complies
9. Additions or alterations to structures and objects shall be done in such a manner that if such additions or alterations were to be removed in the future, the essential form and integrity of the structure would be unimpaired. The new work shall be differentiated from	North and South Elevations (Visible Windows) The original windows on these two elevations were thrown out and thus, lost. The replacement windows are differentiated in material. It is possible to remove the windows in the future and replace them in a manner that does not further alter the historical character of each façade.	Complies
the old and shall be compatible in massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.	East Elevation (Rear Windows) This elevation is not visible from the public way. These windows are not considered character defining due to the location on secondary elevation. The alterations also took place on a non-historic addition. Staff supports replacement of these windows.	Complies
10. Certain building materials are prohibited including the following: Aluminum, asbestos, or vinyl cladding when applied directly to an original or historic material.	Vinyl cladding or aluminum are not part of this alteration.	NA

44 Any mary sign and any	There are no signs aggeriated with this	Mot
11. Any new sign and any	There are no signs associated with this	Not
change in the appearance of	proposal. This standard does not apply.	Applicable
any existing sign located on		11
a landmark site or within the		
H historic preservation		
overlay district, which is		
· /		
visible from any public way		
or open space shall be		
consistent with the historic		
character of the landmark		
site or H historic		
preservation overlay district		
and shall comply with the		
standards outlined in		
chapter 21A.46 of this title.		
1		

ATTACHMENT F: Applicable Design Guidelines

The following are applicable historic design guidelines related to this request. The following applicable design guidelines can be found in A Preservation Handbook for Historic Residential Properties & Districts in Salt Lake City.

http://www.slcdocs.com/historicpreservation/GuideRes/Ch3.pdf

Guideline

- **3.1** The functional and decorative features of a historic window should be preserved.
 - Features important to the character of a window include its frame, sash, muntin, mullions, glazing, sills, heads, jambs, moldings, operation, and the groupings of windows.
 - Frames and sashes should be repaired rather than replaced whenever conditions permit.
- **3.2** The position, number, and arrangement of historic windows in a building wall should be preserved.
 - Enclosing a historic window opening in a key character-defining facade would be inappropriate, as would adding a new window opening.
 - This is especially important on primary facades, where the historic ratio of solid-to void is a character-defining feature. Greater flexibility in installing new windows may be appropriate on rear walls or areas not visible from the public way.
- **3.3** To enhance energy efficiency, a storm window should be used to supplement rather than replace a historic window.
 - Install a storm window on the interior where feasible. This will allow the character of the original window to be seen from the public way.
 - If a storm window is to be installed on the exterior, match the sash design of the original windows. A metal storm window may be appropriate.
 - The storm window should fit tightly within the window opening without the need for sub frames around the perimeter.
 - Match the color of the storm window sash with the color of the window frame; avoid a milled (a silver metallic) aluminum finish if possible.

- Finally, set the sash of the storm window back from the plane of the wall surface as far as possible.
- **3.4** The historic ratio of window openings to solid wall on a primary façade should be preserved.
 - Significantly increasing the amount of glass on a character-defining façade will negatively affect the integrity of the structure
- **3.5** The size and proportion of a historic window opening should be retained.
 - An original opening should not be reduced to accommodate a smaller window, nor increased to receive a larger window, since either is likely to disrupt the design composition.
- **3.6** A replacement window should match the original in its design.
 - If the original window is double-hung, then the replacement window should also be doublehung, or at a minimum appear to be so.
 - Match the replacement also in the number and position of glass panes.
 - Matching the original design is particularly important on key character-defining facades.
- 3.7 Match the profile of the sash and its components, as closely as possible to that of the
- original window.
 - A historic wood window has a complex profile within its casing. The sash steps back to the plane of the glazing (glass) in several increments (see illustrations of frame sections on page 3:9).
 - These increments, which individually are measured in fractions of an inch, are important
 - They distinguish the actual window from the surrounding plane of the wall.
 - The profiles of wood windows allow a double hung window, for example, to bring a rich texture to the simplest structure.
 - These profiles provide accentuated shadow details and depth to the facades of the building. Framing sections, profiles and materials define the type of window and add considerable detail to the facade.

PART II 3:11

Chapter 3. Windows

A Preservation Handbook for Historic Residential Properties & Districts

- In general, it is best to replace wood windows with wood on contributing structures, especially on the primary facades.
- Non-wood materials, such as vinvl or aluminum, will be reviewed on a case-by-case basis. The following will be considered:
- Will the original casing be preserved?
- Will the glazing be substantially diminished?
- What finish is proposed?
- Most importantly, what is the profile?
- 3.8 In a replacement window, use materials that appear similar to the original.
 - Using the same material as the original is preferred, especially on key character-defining
 - A substitute material may be appropriate in secondary locations if the appearance of the window components will match those of the original in dimension, profile, and finish.
 - Installing a non-wood replacement window usually removes the ability to coordinate the windows with an overall color scheme for the house.

ATTACHMENT G: Public Process & Comments

The following is a list of public input opportunities related to the proposal:

Notice of the public hearing for the proposal included:

- Public hearing notice mailed.
- Public notice posted on City and State websites and Planning Division list-serve.
- Public hearing notice sign posted on the property.

Public Input:

As of the publication of this Staff Report, Staff have not received any public comments or questions about the request. If Staff receives any future comments on the proposal, they will be included in the public record and forwarded to the commission.