

# Memorandum

Planning Division Community & Economic Development Department

To:

Historic Landmark Commission

From:

Ray Milliner

Date:

September 1, 2011

Re:

Ronald McDonald House Remodel and Construction of New Building

## Background

On August 18, 2011, the applicant submitted a request to remodel the existing Ronald McDonald house and to construct a new building to the west. The property, located at 901 East South Temple at the corner of M Street and South Temple is zoned RMF-35. The principal use of the property is to provide temporary housing for families of children who are in the hospital.

The purpose of this work session is to gather input from the Historic Landmark Commission regarding the design of the new structure and provide the applicant with feedback prior to the finalization of the drawings and plans. If the Commission finds the plans to be generally favorable, the applicant will finalize the design, and return to the Commission for a public hearing and possible action.

### Proposal

The applicant is proposing to build a 4 story building on the corner of M street and South Temple. The new building is proposed on the former site of a Sinclair gas station, and would be attached to the existing building with a two story atrium / bridge. The south west corner of the building would have a chapel / meditation component on the 4<sup>th</sup> floor with an exterior deck area. Vehicular access to the property would be from M Street to a parking lot located behind the both buildings. Most of the structure will be small residential units, with a proposed a theater, meeting room, and various activity rooms located on the main floor.

### Issues

#### Height

Because of the slope and angle of the lot, the applicant is requesting that the HLC grant a height exception that would range from approximately 10 feet on the south west corner to 3 feet on the north east corner. The purpose of the request is to achieve the density desired, while providing room for the necessary mechanical equipment, duct work and pipes without building the first floor below grade.

To support the request, the applicant has provided analysis of buildings along South Temple that are of a similar or greater height than that proposed. He states that these buildings fit into the surrounding vernacular without a significant impact on adjacent property owners (see height analysis attachment C).

#### Design

The proposed design of the building is a flat roofed brick structure broken into five separate sections. Each section has a small projecting bay with either a pitched roof or arched windows. The base of the structure has a stone wainscot that would run the entire length of the façade. The northwest corner of the building is being designed to accommodate an addition.

## Request

Staff requests that the Historic Landmark Commission review the attached drawings, photos and site plan and provide the applicant with feedback as it relates to the proposed height increase, and the Historic District Design Guidelines.

### Attachments

- A. Proposed elevations
- B. Proposed Floor Plans
- C. Height Analysis

## Attachment A:

Proposed Elevations





























Ronald McDonald House Char


























# Attachment B: Proposed Floor Plans




















# Attachment C: Height Analysis

